

## Pack Code Update Log

Pack Code	Current Description	Change Description	Change date
SB11XIA	modified	corrected components to match print (skido paper)	1/25/2012
HF11XAA	modified	Add option for band seals instead of welds	9/28/2012
HF13XAA	modified	Add option for band seals instead of welds	9/28/2012
HF15XAA	modified	Add option for band seals instead of welds	9/28/2012
HB58XAA	modified	Add option for band seals instead of welds	9/28/2012
HB60XAA	modified	Add option for band seals instead of welds	9/28/2012
HB67XAA	modified	Add option for band seals instead of welds	9/28/2012
SB14XAA	modified	Revise Print to eliminate ref to old NSC code	9/28/2012
TB01XAA	modified	Add McKeesport Tubular, add "No Components"	10/30/2012
TB05XAA	modified	correct picture to show bands as 1-1/4"	10/30/2012
TB06XAA	modified	change from Tubular Processing Services Division to Tubular Threading & Inspection Division	10/30/2012
TD01XAA	modified	change from Texas Operations Division to Tubular Threading & Inspection Division	10/30/2012
HP74XAA	inactivated	Safety reason - shouldn't do cardboard sheet under all bands.	11/2/2012
VF02XTA	Created	Tin Stretch Wrao Pkg Clockwise Coil Wind	11/21/2012
VF03XTA	Created	Tin Stretch Wrao Pkg Counterclockwise Coil Wind	11/21/2012
T1TO	Created	TUBULAR SRVCS - FLTBED CUST RACK TRANSFER	12/4/2012
CP40XAA	Created	Eye Horizontal Paper Wrap Double Loop OD Bands	12/4/2012
CP40TAA	Created	Eye Horizontal Paper Wrap Double Loop OD Bands	12/4/2012
HP01XAA	modified	added step 4 plastic IDP, remove IDP in step 3	12/4/2012
CP40XAA	inactivated	Named Wrong	12/10/2012
HP26TAA	Created	Created tp address HRP&O HSLA > 0.3700"	12/13/2012
TB06XAA	modified	Changed Plant from TSP to TTIS	12/18/2012
HP16CAA	Created	HP16 mandatory Strip Laminate	1/4/2013
HP51CAA	Created	HP51 mandatory Strip Laminate	1/4/2013
HP55CAA	Created	HP55 mandatory Strip Laminate	1/4/2013
HP56CAA	Created	HP56 mandatory Strip Laminate	1/4/2013
HP60CAA	Created	HP60 mandatory Strip Laminate	1/4/2013
CP29XAA	modified	Corrected list of components to match print	1/8/2013
HB04TAA	modified	Corrected list of components to show 2" bands	1/8/2013
HB44XAA	modified	corrected from 3 O/D to 3 I/D bands	1/9/2013
HB69XAA	Created	HR Band, (2) 2" OD band; (6) 2" ID Band	1/14/2013
HF11XAA	modified	Corrected list of components to match print	1/15/2013
HF13XAA	modified	Corrected list of components to match print	1/15/2013
HF16XAA	modified	Corrected list of components to match print	1/15/2013
HP05XAA	modified	Corrected list of components to match print	1/15/2013
HP29HAA	inactivated	Not necessary (only 2 CHAM ordrs for Color Steels )	1/16/2013
HP31XAA	inactivated	Not necessary. Too close to HP01	1/16/2013

## Pack Code Update Log

CP27XAA	modified	corrected list of components to show chip ID rings	1/16/2013
HP73XAA	modified	corrected list of components to show ID ring	1/17/2013
HP88FAA	inactivated	no orders for std HP88 with chipboard donut	1/17/2013
HP89XAA	modified	corrected list of components to match print	1/17/2013
HP87TAA	administrative	associated HP87 picture to SteelTrack	1/17/2013
HP30AAA	modified	corrected list of components to match print	1/18/2013
HP26AAA	inactivated	Not necessary. HP26XAA has Directional Arrow	1/18/2013
HB69TAA	administrative	associated HB69 picture to SteelTrack	1/21/2013
NB12X1A	modified	corrected list of components to 1-1/4" OD band	1/23/2013
NP22XEA	modified	corrected list of components delete OD band; add 1-1/4" ID band	1/23/2013
NP30XEA	modified	corrected list of components from OD to ID bands	1/23/2013
VP21XYA	inactivated	no orders in OPEX or EBS. No Banding spec'd	1/23/2013
HP11XAA	modified	corrected list of components to match print	1/24/2013
HP26MAA	modified	added GCW as plant for this HRP&O code	2/7/2013
CP01TAA	Created	HR Paper Wrap, (2) O/D. (3) I/D all 2"	2/7/2013
GS01KAA	modified	Add 'Y' Modifier - "Fiberboard Core"	3/3/2013
MB19XAA	modified	Added LEW to list of Plants	3/5/2013
HB25YAA	Created	HP25XAA with fiberboard core	3/13/2013
HC02XAA	inactivated	Chipboard wrap over VCI. Code last used 2009	3/26/2013
HP05XAA	inactivated	Double paper wrap not VCI. Obsolete/not used	4/1/2013
HB26XAA	modified	Removed verbiage "If Source is Protec apply VCI Paper secured..."	4/23/2013
CP04XAA	inactivated	no orders in OPEX or EBS.	4/24/2013
CP05HAA	inactivated	no orders in OPEX or EBS.	4/24/2013
CP14XAA	inactivated	no orders in OPEX or EBS.	4/24/2013
CP20XAA	inactivated	no orders in OPEX or EBS.	4/24/2013
CP23XCA	inactivated	no orders in OPEX or EBS.	4/24/2013
CP24XAA	inactivated	no orders in OPEX or EBS.	4/24/2013
CP41XAA	inactivated	no orders in OPEX or EBS.	5/24/2013
CP44XAA	inactivated	no orders in OPEX or EBS.	5/24/2013
CP31XAA	inactivated	no orders in OPEX or EBS.	5/24/2013
TC01VAA	modified	changed print from TCV1	5/28/2013
TB06XAA	modified	changed print from LOAD CODE to PACK CODE TB06	5/28/2013
RGTV	modified	delete from REMARKS - *API Line Pipe - refer to General Information Section 7L0, Page 4, Paragraph 0.12	5/28/2013
RJTW	modified	delete from LOADING PRACTICE - * For Shipments of API Line Pipe - refer to General Information Section 7L0, Page 4, Paragraph 0.12	5/28/2013
CP01TAA	inactivated	no orders in OPEX or EBS.	6/3/2013
HB08PAA	inactivated	no orders in OPEX or EBS.	6/3/2013
HB54XAA	modified	Changed O/D band placement and deleted edge/corner protectors	6/14/2013

## Pack Code Update Log

HB48XAA	inactivated	not used and similar to HB006HAA	6/24/2013
HP24MAA	inactivated	no orders in OPEX or EBS.	6/24/2013
HP18XAA	inactivated	no orders in OPEX or EBS.	6/24/2013
HP18HAA	inactivated	no orders in OPEX or EBS.	6/24/2013
HB63XCA	inactivated	no orders in OPEX or EBS.	6/24/2013
HP84XAA	inactivated	paper cap/chipboard btm deleted a/c lack of use	7/3/2013
HP82XAA	modified	Added Pro-Tec as valid plant	7/8/2013
HP89XAA	modified	Added Pro-Tec as valid plant	7/9/2013
CP33XAA	modified	Corrected stage 2 procedure to match print showing Plastic O.D Protectors	7/23/2013
HB05TAA	inactivated	no orders in OPEX or EBS.	7/30/2013
HB07XAA	inactivated	no orders in OPEX or EBS.	7/30/2013
HB11TAA	inactivated	no orders in OPEX or EBS.	7/30/2013
HB14XAA	inactivated	no orders in OPEX or EBS.	7/30/2013
HB22XAA	inactivated	no orders in OPEX or EBS.	7/30/2013
HB28HAA	inactivated	no orders in OPEX or EBS.	7/30/2013
HB52XAA	inactivated	no orders in OPEX or EBS.	7/30/2013
HP25BAA	inactivated	no orders in OPEX or EBS.	8/1/2013
HP27WAA	inactivated	no orders in OPEX or EBS.	8/1/2013
HP59IAA	inactivated	no orders in OPEX or EBS.	8/8/2013
HP37IAA	inactivated	no orders in OPEX or EBS.	8/8/2013
HP37WAA	inactivated	no orders in OPEX or EBS.	8/8/2013
HP28XAA	inactivated	no orders in OPEX or EBS.	8/8/2013
HP52WAA	inactivated	no orders in OPEX or EBS.	8/8/2013
MP25XAA	Created	Slit Mults - NASG Std #3	8/19/2013
HB63YCA	Created	Eye Horizontal - on Platform - Dust/Paper Cap	8/19/2013
HB54MAA	Created	Eye Horizontal - Bare	8/19/2013
CP40TAA	inactivated	no call for double-loop 2" OD Paper Wrap Pkg.	8/26/2013
HB66XAA	modified	Unapproved HR for this 3/4" band code	9/9/2013
HP02AAA	modified	Unapproved HR for this 3/4" band code	9/9/2013
HP02BAA	modified	Unapproved HR for this 3/4" band code	9/9/2013
HP06AAA	modified	Unapproved HR for this 3/4" band code	9/9/2013
HP27AAA	modified	Unapproved HR for this 3/4" band code	9/9/2013
HP39XAA	modified	Unapproved HR for this 3/4" band code	9/9/2013
HP76HAA	modified	Unapproved HR for this 3/4" band code	9/9/2013
SC01XNA	inactivated	no orders in OPEX or EBS.	9/9/2013
SF04XEA	inactivated	no orders in OPEX or EBS.	9/9/2013
HP39DAA	inactivated	no orders in OPEX or EBS.	9/9/2013
HP48XAA	inactivated	no orders in OPEX or EBS. Essentially same as HP87	9/9/2013
HG10XAA	inactivated	Export Metal Wrap Replaced by Plastic Corrugated.	9/9/2013

## Pack Code Update Log

HB66XAA	modified	Removed Fairfield as approved Plant	9/13/2013
VF01XTA	modified	No Change to Print. Only Added Gary and Midwest as Authorized	10/14/2013
VF02XTA	modified	No Change to Print. Only Added Gary and Midwest as Authorized	10/14/2013
VF03XTA	modified	No Change to Print. Only Added Gary and Midwest as Authorized	10/14/2013
HC06XAA	inactivated	Trial Code. HC07 used instead	10/18/2013
PB03XAA	inactivated	Duplicate of PB04XAA which is used on orders	10/18/2013
PB03XNA	inactivated	Not Necessary	10/18/2013
HP39AAA	modified	No Change to Print. Only Added Gary and Midwest as Authorized	10/22/2013
VP26YEA	Created	Code needed for VP26XEA with Fiber Core	10/23/2013
HP48XAA	reactivated	Reactivated a/c Gary 1st Leg OP code	10/28/2013
HP18XAA	reactivated	Reactivated a/c Gary 1st Leg OP code	10/28/2013
HP01XAA	modified	No change to print. Added Hamilton as approved plant	11/4/2013
T4H0	Created	Created for interworks shipment between Gary tin facilities	11/11/2013
SP25VZZ	Created	Created for shts cut at American Nickeloid for MABE Mexico	12/23/2013
CP05XAA	inactivated	no orders in OPEX or EBS.	1/2/2014
HP61XAA	modified	Added 'VCI' to paper or film in stage 3	1/27/2014
T2H0	Created	Coil, Eye Lengthwise, Flatbed truck with Sidekit	2/5/2014
CP33XAA	modified	Chipboard eyeliner moved from stage 3 to stage 2	2/5/2014
MB16XAA	inactivated	UNUSED CODE FOR USSC.	2/6/2014
NB15XEA	inactivated	UNUSED CODE FOR USSC.	2/6/2014
NB17XEA	inactivated	UNUSED CODE FOR USSC.	2/6/2014
NB18XEA	inactivated	UNUSED CODE FOR USSC.	2/6/2014
NP33XEA	inactivated	UNUSED CODE FOR USSC.	2/6/2014
NP36XEA	inactivated	UNUSED CODE FOR USSC.	2/6/2014
HP39YAA	Created	HP39XAA with fiberboard Core	3/3/2014
CP33AAA	Created	CP33XAA w/Directional Arrow Sticker for GE	3/4/2014
CP33	modified	Edited Print stage 3 to better show eye liner under paper wrap	3/12/2014
CP33	modified	Edited Print to add eye liner over paper in stage 3	3/26/2014
HP42XAA	Created	Alternative to HP61 for Unexposed Auto shipping TX/AL/Mexico	4/22/2014
T1TM	Created	Added Tubular Load Code for Solid Load - End Tarp Only	4/23/2014
BYH0	modified	Updated Title and Description to "Covered Barge"	5/5/2014
HB06DAA	Created	HB06 w/ Plastic Bag over coil	5/7/2014
BZD0	Created	To take place of BYD0 because it doesn't follow naming convention	5/7/2014
HB54MAA	modified	Added Cold Roll as product; Added Hamilton as mill; removed dates from .jpg image.	5/12/2014
HB54MAA	modified	Removed dates from .jpg image	5/12/2014
VP29XEP	Created	Eye Vertical, Platform - Clockwise Wound	5/13/2014
HF08XAA	modified	Removed Hamilton from list of approved plants (no change to print or revision date)	5/19/2014
HF10XAA	modified	Removed Hamilton from list of approved plants (no change to print or revision date)	5/19/2014
HB16XAA	modified	Added MVW and Fairless as approved plants (no change to print or rev. date)	5/22/2014

## Pack Code Update Log

HB56XAA	modified	Added Hamilton to list of approved plants (no change to print or rev. date)	5/30/2014
HB03XAA	modified	Added Hamilton to list of approved plants (no change to print or rev. date)	5/30/2014
HP06AAA	inactivated	No orders in EBS	6/4/2014
VP26XEA	modified	Added note to use ISPM-15 compliant pallets for Mexico shipments. Added CHAM and FRLS	6/6/2014
HF07XAA	modified	Changed print to show 2 bands since >= 45" is the common case	6/18/2014
MB20XAA	Created	Added per NARMCO Reqs	6/24/2014
VP10XAA	Created	New Tin "Universal" Package Code. No winding specified.	6/24/2014
HP27CAA	inactivated	No orders in EBS	6/30/2014
HP27MAA	inactivated	No orders in EBS	6/30/2014
HP72XAA	inactivated	No orders in EBS	6/30/2014
HP77JAA	inactivated	No orders in EBS	6/30/2014
HP78IAA	inactivated	No orders in EBS	6/30/2014
HP87AAA	inactivated	No orders in EBS	6/30/2014
HP88MAA	inactivated	No orders in EBS	6/30/2014
HP30AAA	modified	Added Fairfield to list of approved plants (no change to print or revision date)	7/1/2014
VP10XAP	Created	Tin "Universal" Package for Clockwise winding specified	7/2/2014
VP10XAR	Created	Tin "Universal" Package for CounterClockwise winding specified	7/2/2014
HB51XAA	modified	list of components mistakenly showed plastic I.D Core instead of plastic I.D. Ring	7/30/2014
CP27XAA	inactivated	No orders since 2012 and then only for 1 part	8/6/2014
CP13XAA	inactivated	No orders since 2012	8/8/2014
CP39XAA	modified	Break into 3 Stages to Better Illustrate 1 I.D. Band Under I.D. Protector	10/8/2014
HB26DAA	modified	Removed verbiage "If Source is Protec apply VCI Paper secured..."	10/8/2014
T2GO	Created	COIL-EYE TO REAR OR SIDE - FLATBED W/SIDEKIT	10/28/2014
HF05XAA	Created	Stretch Wrap - Winter Wrap / Export	10/29/2014
HP39YAA	modified	Added Fairfield to list of approved plants (no change to print or revision date)	12/15/2014
HB03XAA	modified	Corner Protectors and Seal Pads are not required on Hot Rolled Mill Edge Coils, or <b>PROTEC Full Hard</b>	12/15/2014
HB03HAA	modified	Corner Protectors and Seal Pads are not required on Hot Rolled Mill Edge Coils, or <b>PROTEC Full Hard</b>	12/15/2014
HB03TAA	modified	Corner Protectors and Seal Pads are not required on Hot Rolled Mill Edge Coils, or <b>PROTEC Full Hard</b>	12/15/2014
HF05XAA	modified	changed so all configurations are double wrap Panacea plastic	12/16/2014
CP33XAA	modified	Added 2 more Plastic ID Bands; Bands at 2, 4, 8, and 10 o'clock Positions	12/26/2014
CP34XAA	inactivated	No orders last 4 years	1/12/2015
CP36XAA	modified	Added 2 more Plastic ID Bands; Bands at 2, 4, 8, and 10 o'clock Positions	1/13/2015
NB28FSD	Created	Eye Vertical, Platform -w/Donuts & if multiple then spacers	2/3/2015
HP42XAA	modified	Added 2nd S/W donut and additional ID Band	2/12/2015
NP22XEA	modified	Added Pro-Tec as valid plant	2/12/2015

## Pack Code Update Log

RJTQ	inactivated	not needed	2/13/2015
RJTR	inactivated	not needed	2/13/2015
RJTW	inactivated	not needed	2/13/2015
T1T0	inactivated	not needed	2/16/2015
T1T1	inactivated	not needed	2/16/2015
T5T0	modified	Renamed 'Couplings - Dry Van'	2/16/2015
T5T1	Created	Couplings - flatbed w/Tarp	2/16/2015
PP04XLA	Created	Plate - Paper Wrap - 4"x4" Longitudinal Runners	2/18/2015
SP17X5A	inactivated	No orders in EBS	2/18/2015
HF06XAA	Created	Stretch Wrap - Only 1 O/D Band	2/23/2015
HF04MAA	Created	Stretch Wrap - Only 1 O/D Band and no O/D or I/D Protectors	3/12/2015
HF06BAA	Created	Stretch Wrap - Double Wrap - Only 1 O/D Band	3/19/2015
T1TC	modified	Added verbiage about Alaska Loads and BP Spec	4/6/2015
RGTU	modified	Added verbiage about Alaska Loads and BP Spec and TSA Spec	4/17/2015
HF06AAA	Created	HF06 with Directional Arrow	4/20/2015
NP24GSA	Created	NP24XSA with Sidewall Donuts	5/8/2015
VP12XTA	inactivated	not needed	5/18/2015
VP01XTF	inactivated	not needed	5/18/2015
VP05XTA	inactivated	not needed	5/18/2015
VP02XTA	inactivated	not needed	5/18/2015
VP04XTA	inactivated	not needed	5/18/2015
VF01XTA	inactivated	not needed	5/18/2015
VP30XTA	inactivated	not needed	5/18/2015
VF02XTA	inactivated	not needed	5/18/2015
VF03XTA	inactivated	not needed	5/18/2015
RGTA	modified	Revised to comply to AAR Fig 124-A	5/18/2015
RGTB	modified	Revised to comply to AAR Fig 124-A	5/18/2015
RGTP	modified	Revised to comply to AAR Fig 124-A	5/18/2015
RGTU	modified	Revised to comply to AAR Fig 124-A	5/18/2015
RGTY	modified	Revised to comply to AAR Fig 124-A	5/18/2015
RGT4	modified	Revised to comply to AAR Fig 124-A	5/18/2015
RGTV	modified	Revised to comply to AAR Fig 126 and current mill practice	5/19/2015
RGT0	inactivated	not needed	5/19/2015
NF01XEA	Created	Mults eye vertical, stretch wrapped to platform	6/17/2015
RGTA	modified	Edited per CI Project to add more verbiage	5/18/2015
RGTB	modified	Edited per CI Project to add more verbiage	5/18/2015
RGTP	modified	Edited per CI Project to add more verbiage	5/18/2015
RGTU	modified	Edited per CI Project to add more verbiage	5/18/2015
RGTY	modified	Edited per CI Project to add more verbiage	5/18/2015

## Pack Code Update Log

RGT4	modified	Edited per CI Project to add more verbiage	5/18/2015
RGTV	modified	Edited per CI Project to add more verbiage	5/19/2015
T4H1	Created	For Brampton Stamping	6/29/2015
HB08XAA	inactivated	no orders in 2013, 2014, 2015	7/14/2015
HB27XAA	inactivated	no orders in 2013, 2014, 2015	7/14/2015
HB28XAA	inactivated	no orders in 2013, 2014, 2015	7/14/2015
HB49XAA	inactivated	no orders in 2013, 2014, 2015	7/14/2015
HB50XAA	inactivated	no orders in 2013, 2014, 2015	7/14/2015
HC04XAA	inactivated	no orders in 2013, 2014, 2015	7/14/2015
NF01XER	Created	Mults eye vertical, stretch wrapped to platform; counterclockwise wound	7/14/2015
SP11XIA	modified	changed runners from 2x4 to 4x4 (SP14XIA was identical with 2x4 runners)	8/19/2015
HC07XAA	modified	added note to bottom of print "Sidewall donuts Must Provide 100% Sidewall Coverage"	9/10/2015